

L Number	Hits	Search Text	DB	Time stamp
1	34346	cable near4 (tension pull tes\$4)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/23 08:21
2	3892	cable near4 (tension pull tes\$4).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/23 08:23
7	1152	tensiometer	USPAT	2001/04/23 08:46
8	12	(tensiometer and cable).clm.	USPAT	2001/04/23 08:46
-	86	73/862.391.cccls.	USPAT	2001/04/21 19:24
-	1	73/862\$3.cccls. and (measure and (stress tension strain) and (hook hanger) and hydraulic).clm.	USPAT	2001/04/19 13:00
-	3	73/862\$3.cccls. and (measure and (stress tension strain) and (hook hanger handle) and hydraulic and gage)	USPAT	2001/04/19 13:02
-	6	73/862\$3.cccls. and (measure and (stress tension strain) and cable and hydraulic and gage)	USPAT	2001/04/21 19:28
-	0	73/\$6.cccls. and (measure and (stress tension strain) and cable and hydraulic and gage and hook and V near2 shape).clm.	USPAT	2001/04/19 13:06
-	0	73/\$6.cccls. and (measure and (stress tension strain) and cable and hydraulic and gage and hook and V near2 shape)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:06
-	0	73/\$6.cccls. and (measure and (stress tension strain) and cable and hydraulic and gage ).clm.	USPAT	2001/04/19 13:07
-	43	73/\$6.cccls. and (measure and (stress tension strain) and cable and hydraulic and gage )	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:08
-	1	73/\$6.cccls. and (measure and (stress tension strain) and cable and hydraulic and (gage gauge)).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:09
-	137	73/\$6.cccls. and (measure and (stress tension strain) and (cable line wire) and hydraulic and gage )	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:10
-	505	73/\$6.cccls. and (measure and (stress tension strain) and (cable line wire) and hydraulic and (gage gauge))	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:10
-	4	73/\$6.cccls. and (measure and (stress tension strain) and (cable line wire) and hydraulic and (gage gauge)).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:14
-	0	73/144.cccls.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:12
-	5	3839908.pn.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:12
-	11	(measure and (stress tension strain weigh) and (cable line wire) and hydraulic and (gage gauge)).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:18
-	0	(measure and (stress tension strain weigh) and (cable line wire) and (v near shape) and (gage gauge)).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:18
-	0	(measure and (stress tension strain weigh) and (cable line wire) and (v near4 shape) and (gage gauge)).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:20

-	1	(measure and (stress tension strain weigh) and (cable line wire) and (v near4 shape) ).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:19
-	80484	(stress tension strain weigh) and (cable line wire).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:22
-	10275	((stress tension strain weigh) and (cable line wire).clm.) and measure	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:20
-	1025	((stress tension strain weigh) and (cable line wire).clm.) and measure.clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:20
-	122	((stress tension strain weigh) and (cable line wire).clm.) and measure.clm.) and (gage gauge).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:21
-	11	((stress tension strain weigh) and (cable line wire).clm.) and measure.clm.) and (gage gauge).clm.) and jack	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:21
-	39113	(stress tension strain weigh) and (cable wire).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:22
-	18	((stress tension strain weigh) and (cable wire).clm.) and measure and jack and (gage gauge).clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:26
-	159546	wire near stain naear gauge	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:27
-	2	wire near stain near gauge	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:27
-	5	(wire cord cable) near (stain force stress) near gauge	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:38
-	146	(wire cord cable) near4 (stain force stress) near4 gauge	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:38
-	109420	deflect(wire cord cable) near4 (stain force stress) near4 gauge	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:59
-	21	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect deflection)	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:57
-	9	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect deflection) and pull	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 13:57
-	3	deflect and(wire cord cable) near4 (stain force stress) near4 (gauge gage)and pull	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 14:02
-	856	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 14:43

-	3	deflect and(wire cable) near4 (stain force stress) near4 (measure\$4)and pull	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 14:03
-	16	73/862.39\$.ccls. and pull and cable	USPAT	2001/04/19 14:15
-	82	73/862.451.cccls.	USPAT	2001/04/19 14:27
-	4	73/862.42.cccls. and pull and cable	USPAT	2001/04/19 14:24
-	205	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull and hydraulic	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 14:44
-	38	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull and hydraulic .clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 14:45
-	0	(deflect and(wire cable) and (stain force stress) and (measure\$4)and pull and hydraulic) .clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/19 14:46
-	1	(deflect and(wire cable) and (stain force stress) and hydraulic) .clm.	USPAT; EPO; JPO; Derwent; IBM TDB	2001/04/23 08:15
-	6	73/862.391.cccls. and hydraulic	USPAT	2001/04/21 19:25
-	1	73/862.391.cccls. and (hydraulic).clm.	USPAT	2001/04/21 19:25
-	0	73/862\$3.cccls. and (measure and (stress tension strain) and cable and hydraulic and gage).clm.	USPAT	2001/04/23 08:46
-	2	73/862\$3.cccls. and (measure and (stress tension strain) and hydraulic and gage).clm.	USPAT	2001/04/21 19:29
-	1	73/\$6.cccls. and (measure and deflection and hydraulic and gage).clm.	USPAT	2001/04/21 19:30
-	538	(measure and deflection cable and hydraulic and gage).clm.	USPAT	2001/04/21 19:38
-	4	(measu\$4 and deflect\$4 and cable and hydraulic and (gauge gage)).clm.	USPAT	2001/04/21 19:32
-	12	(measu\$4 and cable near4 deflect\$4 and hydraulic and (gauge gage))	USPAT	2001/04/21 19:36
-	1	(tensiometer and cable near4 deflect\$4 and hydraulic and (gauge gage)).clm.	USPAT	2001/04/21 19:36
-	535	(measure and deflection cable and hydraulic near4 jack and gage).clm.	USPAT	2001/04/21 19:39
-	535	(measure and deflection cable and hydraulic near jack and gage).clm.	USPAT	2001/04/21 19:39
-	42	(tensio\$4 and measure and deflection cable and hydraulic near jack and (gage gauge)).clm.	USPAT	2001/04/21 19:50
-	3	(tensio\$4 and pull near4 test\$4 and deflection cable and hydraulic near jack and (gage gauge)).clm.	USPAT	2001/04/21 19:51